Division of Health Service Regulation							E SURVEY
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:			n. I '	(X2) MULTIPLE CONSTRUCTION (X3) DA A. BUILDING: 01		CO	MPLETED
AND FEMALOI CONTRACTOR		1	A. BOILDING, 41				
		HAL081051	В	B. WING		00	/01/2016
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE							
2270 OAKLAND ROAD							
NANAS ASSISTED LIVING FACILITY # 2 FOREST CITY, NC 28043							
(X4) ID SUMMARY STATEMENT OF DEFICIENCIES PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION)			L N}	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		COMPLETE DATE
C 000	Initial Comments			C 000			
	Report of Complain 6-1-2016.	nt Survey by Dennis Harr	rell on				
	licensed on 6-1-19 this information, we meet the 1967 Edil Building Code, the of Adult Care Home	nat this facility was first 68, for 44 residents. Base are requiring the facility tion of the North Carolina 1971 Rules for the Liceres, and the applicable posts.	y to a State nsing ortions				
,	The complaint alle conditions due to s with gas logs.	ged poor environmental soot accumulation at a fir	replace				
	The complaint was were cited that will	s substantiated and defice require a plan of correct	tion.				
C 164	Housekeeping and	d Furnishings-Clean, Rep	paired	C 164	:		stad 7/201
	10A NCAC 13F .0: FURNISHINGS (a) Adult care hom (1) have walls, ce coverings kept cle (2) have no chron (3) have furniture	PHYSICAL PLANT 306 HOUSEKEEPING nes shall: ellings, and floors or floor ean and in good repair; nic unpleasant odors; clean and in good repair ll apply to new and existi	ir;		Ceiling will be	par	
	Based on observa accumulation of s	net as evidenced by: ation, there was a signific oot on the walls, ceiling a half of the living room.	cant and	4			
Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE OF THE PROVIDER O							(X5) DATE
							tinuation sheet 1 of 2

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION DENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING HAL081051 06/01/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2270 OAKLAND ROAD NANAS ASSISTED LIVING FACILITY # 2 FOREST CITY, NC 28043 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION PRÉFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE COMPLETE REGULATORY OR LSC IDENTIFYING INFORMATION) "AG TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) C 191 | Continued From page 1 C 191 C 191 Unvented & Portable Elec. Heaters Prohibited C 191 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (b) There shall be a heating system sufficient to Gas off maintain 75 degrees F (24 degrees C) under winter design conditions. In addition, the and removed gas palle 1005 and a sign 169/16 has been put up to let staff know not to upe following shall apply to heaters and cooking appliances. (2) Unvented fuel burning room heaters and portable electric heaters are prohibited. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: Based on observation the facility failed to adhere to the prohibition on unvented fuel burning heaters. Unvented heaters are a potential health hazard and as such could effect all occupants of the facility. Finding includes: There was an unvented fireplace with gas logs in the living room. Division of Health Service Regulation STATE FORM

2ZC221

Division of Health Service Regulation

If continuation sheet 2 of 2